

## **Captions for 11/29 RAB presentation/slide show**

1. Cover slide—no caption
2. Parcel B soil excavation—large excavation in IR-07
3. Parcel B soil excavation—excavating and loading soil
4. Parcel B soil excavation—surveying excavation boundaries
5. Parcel B soil excavation—trucking in clean backfill material
6. Parcel B soil excavation—compacting clean backfill
7. Parcel B soil excavation—screening stockpiled soil for radiation
8. Parcel B soil excavation—screening stockpiled soil for radiation
9. Parcel B soil excavation—weighing truck on scale
10. Parcel B soil excavation—scale readout to determine weight of load
11. Parcel B soil excavation—covering soil load in truck
12. Parcel B soil excavation—tying down cover for soil load in truck
13. Parcel B soil excavation—investigating excavation bottom
14. Parcel B soil excavation—repairing damaged utility line
15. Parcel B soil excavation—off-site investigation at western boundary
16. Parcel B drain line removal—industrial drain line along Lockwood St
17. Parcel B drain line removal—removing soil over drain line
18. Parcel B drain line removal—removing drain pipe and loading into truck
19. Parcel B drain line removal—excavating along drain line
20. Parcel B drain line removal—excavating along drain line
21. Parcel B drain line removal—drain line trench following excavation
22. Parcel C steam line removal—open utility corridor with insulated steam line
23. Parcel C steam line removal—removing asbestos insulation on steam line
24. Parcel C steam line removal—tapping into steam line to test for waste oil
25. Parcel C steam line removal—cleaning out steam line

26. Parcel D steam line removal—direct buried steam line
27. Parcel D steam line removal—excavating outside utility corridor
28. Parcel D steam line removal— tapping into steam line in dry dock utility corridor for investigation after asbestos removal
29. Parcel D steam line removal— removing asbestos insulation on steam line in dry dock utility corridor
30. Parcel D soil excavation—excavation at IR-08 near Building 606
31. Parcel C soil excavation—excavation at IR-28 near Building 281
32. Parcel D soil excavation—excavation at IR-08 near Building 606
33. Parcel C soil excavation—excavation around utility line near Building 281
34. Parcel C soil excavation—removing large boulders at excavation near Building 231
35. Parcel C soil excavation—local trucking firm
36. Parcel C soil excavation—local trucking firm
37. Dry Dock 4 removal action—view of dry dock toward SF Bay, two drainage culverts run along the length of the dry dock floor
38. Dry Dock 4 removal action—lowering heavy equipment to dry dock floor
39. Dry Dock 4 removal action—mobilizing equipment to dry dock floor
40. Dry Dock 4 removal action—pumping out liquid and loose sediment from culverts
41. Dry Dock 4 removal action—pumping out liquid and loose sediment from culverts
42. Dry Dock 4 removal action—pumping out liquid and loose sediment from culverts
43. Dry Dock 4 removal action—placing forms at end of culvert prior to concrete placement
44. Dry Dock 4 removal action—concrete trucks lined up outside of dry dock
45. Dry Dock 4 removal action—concrete pumped from trucks using a boom
46. Dry Dock 4 removal action—concrete placement within culverts
47. Dry Dock 4 removal action—bins containing removed sediment and liquid from culverts
48. Dry Dock 4 removal action—solidified sediment chunk removed from culvert
49. Radiation removal action—excavation at Building 364 along pipe trench
50. Radiation removal action—excavation at Building 364 along pipe trench

51. Radiation removal action—excavation at Building 364 along pipe trench
52. Radiation removal action—typical pipe removed from trench
53. Radiation investigation—screening sampling along Parcel E shoreline
54. Parcel E landfill cap—aerial view of liner associated with landfill cap
55. Parcel E landfill cap—aerial view of liner associated with landfill cap
56. Parcel E landfill cap—maintenance of vegetative cover to improve grass growth
57. Parcel E landfill cap—watering of vegetative cover
58. Parcel E landfill cap—current status of vegetative cover
59. Parcel E landfill cap— current status of vegetative cover
60. Soil import from BART—clean backfill being stockpiled in Parcel E near Building 600
61. Soil import from BART—managing soil stockpile using emulsifiers to minimize dust
62. Soil import from BART—managing soil stockpile using emulsifiers to minimize dust
63. Soil import from BART—managing soil stockpile using emulsifiers to minimize dust
64. Parcel F investigation—offshore sampling associated with validation study
65. Parcel F investigation—offshore sampling associated with validation study
66. Parcel F investigation—samplers retrieving sediment samples
67. Parcel F investigation—samplers retrieving sediment samples
68. Petroleum hydrocarbon investigation—soil boring marked prior to drilling
69. Petroleum hydrocarbon investigation—drilling soil boring using direct push rig
70. Petroleum hydrocarbon investigation—monitoring air using photo-ionization detector (PID) during drilling
71. Petroleum hydrocarbon investigation—assessing contamination of soil sample using PID after drilling
72. Petroleum hydrocarbon investigation—collecting soil sample for gasoline analysis using Encore sampler



# Hunters Point Shipyard Environmental Cleanup Program Update

November 29, 2001





































